

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
1	BRS	2107	(white calibration) adj (strip member board)	USPAT; US-PGPUB; EPO; JPO	2002/12/19 07:13		
2	BRS	35	(first second two) adj ((white calibration) adj (strip member board))	USPAT; US-PGPUB; EPO; JPO	2002/12/23 13:41		
3	BRS	1	(358/496.ccls. or 358/497.ccls.) and ((first second two) adj ((white calibration) adj (strip member board)))	USPAT; US-PGPUB; EPO; JPO	2002/12/21 12:23		
4	BRS	1	(358/496.ccls.) and ((first second two) adj ((white calibration) adj (strip member board)))	USPAT; US-PGPUB; EPO; JPO	2002/12/21 12:24		
5	BRS	15	4907097.URPN.	USPAT	2002/12/21 13:12		
6	BRS	15	4907097.URPN.	USPAT	2002/12/21 13:36		
7	BRS	3	("4578711" "4622594" "4717963").PN.	USPAT	2002/12/21 13:37		
8	BRS	1	ADF and (first second two) adj ((white calibration) adj (strip member board))	USPAT; US-PGPUB; EPO; JPO	2002/12/23 11:12		
9	BRS	751	358/406.ccls.	USPAT; US-PGPUB; EPO; JPO	2002/12/23 13:41		
10	BRS	392	358/461.ccls.	USPAT; US-PGPUB; EPO; JPO	2002/12/23 13:41		
11	BRS	1767	358/474.ccls.	USPAT; US-PGPUB; EPO; JPO	2002/12/23 13:41		
12	BRS	1	358/474.ccls. and ((first second two) adj ((white calibration) adj (strip member board)))	USPAT; US-PGPUB; EPO; JPO	2002/12/23 13:43		
13	BRS	1	5864408.pn.	USPAT; US-PGPUB; EPO; JPO	2002/12/23 13:45		
14	BRS	36	(second near5 ((black white) near5 board))	USPAT	2003/06/09 11:36		

Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
15 BRS	1	((second near5 ((black white) near5 board))) and (correct\$3 adjust\$3) near5 (light near5 (intensity quantity bright\$4))	USPAT	2003/06/09 12:52		
16 BRS	1	((second near5 ((black white) near5 board))) and (correct\$3 adjust\$3) same (light same (intensity quantity bright\$4))	USPAT	2003/06/09 11:42		
17 BRS	101	(reference near5 (board strip)) and ((correct\$3 adjust\$3) near5 ((light illuminat\$3 lamp)) near5 (intensity quantity bright\$4))	USPAT	2003/06/09 12:11		
18 BRS	0	6323933.URPN.	USPAT	2003/06/09 11:51		
19 BRS	4	("5146351" "5745253" "6088138" "6122077").PN.	USPAT	2003/06/09 11:51		
20 BRS	1	6032864.pn.	USPAT	2003/06/09 12:11		
21 BRS	1	((second near5 ((black white) near5 board))) and (correct\$3 adjust\$3) near5 ((light illuminat\$3 lamp) near5 (intensity quantity bright\$4))	USPAT	2003/06/09 13:51		
22 BRS	1	((second near5 ((black white) near5 board))) and (correct\$3 adjust\$3 control\$3) near5 (light near5 (intensity quantity bright\$4))	USPAT	2003/06/09 12:53		
23 BRS	15401	(correct\$3 adjust\$3 control\$3) near5 (light near5 (intensity quantity bright\$4))	USPAT	2003/06/09 16:07		
24 BRS	343	((correct\$3 adjust\$3 control\$3) near5 (light near5 (intensity quantity bright\$4))) and (image adj (reader scanner))	USPAT	2003/06/09 12:55		

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
25	BRS	1	((correct\$3 adjust\$3 control\$3) near5 (light near5 (intensity quantity (brightness\$4)) and (image adj (reader scanner))) and (second near5 ((white black) near5 board)))	USPAT	2003/06/09 13:17		
26	BRS	1	5864408.pn.	USPAT	2003/06/09 13:17		
27	BRS	2	5864408.URPN.	USPAT	2003/06/09 13:17		
28	BRS	18	("4958825" "5075539" "5077585" "5100022" "5104109" "5313312" "5379095" "5485263" "5513017" "5523848" "5537214" "5537219" "5638189" "5717200" "5856879" "5864408" "5878319" "5909290").PN.	USPAT	2003/06/09 13:39		
29	BRS	1	((second near5 ((black white) near5 board))) and ((light illumination) near7 control)	USPAT	2003/06/09 13:55		
30	BRS	301318	(change vary adjust control) same (light lamp illumination intensity bright\$4)	USPAT	2003/06/09 16:16		
31	BRS	144763	(change vary adjust control) near7 (light lamp illumination intensity bright\$4)	USPAT	2003/06/09 13:59		
32	BRS	1445	((change vary adjust control) near7 (light lamp illumination intensity bright\$4)) and (image adj (reader scanner))	USPAT	2003/06/09 14:00		
33	BRS	1434	((change vary adjust control) near7 (light lamp illumination intensity bright\$4)) and (image adj (reader scanner))) and (second (black white reference))	USPAT	2003/06/09 14:01		

Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
34 BRS	97	((change vary adjust control) near7 (light lamp illumination intensity bright\$4)) and (image adj (reader scanner)) and ((second (black white reference)) near7 board)	USPAT	2003/06/09 15:09		
35 BRS	0	difference near7 ((light near7 second) near5 (white adj board))	USPAT	2003/06/09 15:12		
36 BRS	0	difference same ((light near7 second) near5 (white adj board))	USPAT	2003/06/09 15:12		
37 BRS	70	358/475.ccls. and ((correct\$3 adjust\$3 control\$3) near5 (light near5 (intensity quantity bright\$4)))	USPAT	2003/06/09 16:08		
38 BRS	12	((change vary adjust control) same (light lamp illumination intensity bright\$4)) and 358/475.ccls.) and (second near3 (white black))	USPAT	2003/06/09 16:17		
39 BRS	239	((change vary adjust control) same (light lamp illumination intensity bright\$4)) and 358/475.ccls.	USPAT	2003/06/10 08:48		
40 BRS	240	((change vary adjust control) same (light lamp illumination intensity bright\$4)) and 358/475.ccls.	USPAT	2003/06/10 08:49		
41 BRS	0	((change vary adjust control) same (light lamp illumination intensity bright\$4)) and 358/475.ccls.) and ((first second) near3 (white adj board))	USPAT	2003/06/10 08:51		

Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
42 BRS	0	((change vary adjust control) same (light lamp illumination intensity bright\$4)) and 358/475.ccls.) and ((first second) near3 ((white reference black) adj board))	USPAT	2003/06/10 08:52		
43 BRS	1	((change vary adjust control) same (light lamp illumination intensity bright\$4)) and 358/475.ccls.) and ((first second) near7 ((white reference black) near5 board))	USPAT	2003/06/10 08:53		
44 BRS	7	5249068.URPN.	USPAT	2003/06/10 08:58		
45 BRS	13	("4660082" "4829379" "4868685" "4870501" "4916549" "4989100" "5062144" "5070414" "5099341" "5101281" "5105286" "5146351" "5157518").PN.	USPAT	2003/06/10 09:07		
46 BRS	11	5099341.URPN.	USPAT	2003/06/10 11:57		
47 BRS	1	5099341.pn.	USPAT	2003/06/11 16:49		
48 BRS	1	5099341.pn. and ((first second) near7 (white adj reference))	USPAT	2003/06/11 16:51		